Oil Field Environmental Incident Summary

Responsible Party: WHITING OIL AND GAS CORPORATION **Well Operator:** WHITING OIL AND GAS CORPORATION

Well Name: SMOKEY 2-17-5-3H3

Field Name: PEMBROKE Well File #: 24901

Date Incident:6/2/2016Time Incident:16:30Facility ID Number:County:MCKENZIETwp:149Rng:98Sec:17Qtr:

Location Description:

Submitted By: Patrick McNamara Received By:

Contact Person: Patrick McNamara

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.3 MileDistance Nearest Water Well:0.3 Mile

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No **Units** Spilled Recovered Units **Followup Units** Oil 10 **Barrels** 10 **Barrels** 10 barrels **Brine** 15 **Barrels** 15 **Barrels** 15 barrels

15

Barrels

15

barrels

Description of Other Released Contaminant:

Due to recent rains, roughly 15 bbl of freshwater was also recovered.

Inspected: Written Report Received: 6/17/2016 Clean Up Concluded: 6/4/2016

Risk Evaluation:
None noted.

Other

Areal Extent:

Potential Environmental Impacts:

Minimal impact to well facility soil.

Action Taken or Planned:

Treater burners were shut off, well was shut in, cleanup truck was called and the gasket on the manway cover was replaced.

Monitor treater pressure as to not over pressure the treater. Daily inspection of integrity of the gaskets. Make sure that all bolts are tightened to specs.

Wastes Disposal Location: Fluids were put back in tanks on site. Impacted well facility soil will be disposed of at an approved facility.

Agencies Involved:

Updates

Date: 6/3/2016 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.